

WEST WALL FAILURE



WEST WALL FAILURE



POST FAILURE TEMPORARY WALL BRACING SUPPORT AT WEST WALL



POST FAILURE TEMPORARY WALL BRACING SUPPORT AT WEST WALL



SOUTH EXTERIOR VIEW



EAST EXTERIOR VIEW



NORTH EXTERIOR VIEW



NORTH EXTERIOR VIEW - DOOR TO APARTMENTS



NORTH EXTERIOR VIEW - ENLARGED PARTIAL PICTURE



NORTH EXTERIOR VIEW - ENLARGED PARTIAL PICTURE



NORTH EXTERIOR VIEW - LEADED GLASS



NORTH EXTERIOR VIEW - LEADED GLASS



INTERIOR VIEW OF SEPARATION AT WALL/FLOOR ABUTMENT



INTERIOR VIEW OF MAJOR WALL AND CEILING DIFFERENTIAL MOVEMENT



INTERIOR VIEW OF DAYLIGHT PENETRATING THROUGH
WALL/FLOOR ABUTMENT



WEST WALL WITH 4 YEAR MIN TEMPORARY WALL BRACING



WEST AND WEST EXTERIOR VIEWS




CURRENT CONTEXTUAL NORTH EXTERIOR VIEWS




CURRENT CONTEXTUAL NORTH EXTERIOR VIEWS



CURRENT CONTEXTUAL NORTH EXTERIOR VIEWS



CURRENT INTERIOR CONDITIONS



CURRENT INTERIOR CONDITIONS



CURRENT INTERIOR CONDITIONS



CURRENT INTERIOR CONDITIONS