

RESOLUTION NO. 2024-_____

RE: CERTIFICATE OF APPROPRIATENESS UNDER THE PROVISIONS
OF THE ACT OF PENNSYLVANIA LEGISLATURE 1961, JUNE 13, P.
L. 282 (53 SECTION 8004) AND BETHLEHEM ORDINANCE NO. 3952
AS AMENDED.

The applicant/owner of the property located at 459 Old York Road proposes to reconstruct an original dormer, install exterior house lighting, and paint trim and shutters.

NOW, THEREFORE, BE IT RESOLVED by the Council of the City of Bethlehem that a Certificate of Appropriateness is hereby granted for the proposal.

Sponsored by: /s/ _____

/s/ _____

ADOPTED BY THE COUNCIL THIS _____ DAY OF _____, 2024.

/s/ _____
President of Council

ATTEST:

/s/ _____
City Clerk

HISTORICAL & ARCHITECTURAL REVIEW BOARD

APPLICATION #11: The applicant/owner of the property located at 459 Old York Road proposes to reconstruct an original dormer, install exterior house lighting, and paint trim and shutters.

OWNER: Historic Bethlehem Museums & Sites
74 Broad Street, Suite 310
Bethlehem, PA 18018

The Board upon motion by Michael Simonson and seconded by Diana Hodgson adopted the proposal that City Council issue a Certificate of Appropriateness for the reconstruction of an original dormer, installation of exterior house lighting, and painting of trim and shutters, with the following conditions;

1. Double hung windows in the stone portion of the building will be changed from the 6 over 6 lite windows shown on drawing A201 to 2 over 2 lite double hung windows that were found to be more historically accurate.
2. The color of the trim shall be SW 2829 Classical White.
3. The color of the shutters shall be SW 6209 Ripe Olive.
4. The color of the lantern sconce and emergency lighting fixtures shall be black.
5. Applicant shall come back to HARB at a future meeting for review of signage and any other elements of work that have not been previously approved and are not specifically approved above.

The vote was unanimous to approve the reconstruction of an original dormer, installation of exterior house lighting, and painting of trim and shutters, as per the motion.

Guideline Citation:

Secretary of Interior Standards No.(s)

#2 The historic character of a property shall be retained and preserved. The removal of historic materials or alteration of features and spaces that characterize a property shall be avoided.

#5 Distinctive features, finishes, and construction techniques or examples of craftsmanship that characterize a property shall be preserved.

#6 Deteriorated historic features shall be repaired rather than replaced. Where the severity of deterioration requires replacement of a distinctive feature, the new feature shall match the old in design, color, texture, and other visual qualities and, where possible, materials. Replacement of missing features shall be substantiated by documentary, physical, or pictorial evidence.

#9 New additions, exterior alterations, or related new construction will not destroy historic materials, features, and spatial relationships that characterize the property. The new work shall be differentiated

from the old and will be compatible with historic materials, features, size, scale and proportion, and massing to protect the integrity of the historic property and its environment.

#10 New additions and adjacent or related new construction will be undertaken in such manner that, if removed in the future, the essential form and integrity of the historic property and its environment would be unimpaired.

Bethlehem Historic District Design Guidelines

Page 8: Exterior Woodwork & Siding:

The HARB encourages,

- Regularly maintaining and repainting exterior woodwork including repainting, and addressing potential areas of moisture including clogged gutters and downspouts, groundwater, leaky pipes, and interior condensation
- Retaining decorative woodwork since it is a character defining element that can be difficult to replace
- Repairing smaller areas of deterioration by reinforcing or patching – small cracks and checks can be repaired with an exterior wood filler, glue, or epoxy – Loose elements can be refastened with nailing or drilling and screwing
- Selectively replacing deteriorated wood elements that are beyond repair with wood pieces that match the size, profile, exposure and pattern, and character of the historic wood element – Wood filler in the joints between the new and old wood will help provide a smooth finish
- Large scale or significant replacement of exterior wood siding with paintable material that match the size, profile, exposure, pattern, and character of the historic wood

The HARB discourages,

- Removing or encapsulating with vinyl or aluminum siding, trim, decorative features, and trim elements such as brackets, spindles, cornices, columns, posts, etc.
- Installing non-wood trim

Page 8: Paint:

The HARB encourages,

- Hand washing with mild detergent and bristle brush, hand scraping, and hand sanding

The HARB discourages,

- Rotary tools – disks can leave circular marks and wires can tear into the surface
- Heat guns and heat plate – can ignite paint or underlying surface if left in one location too long

- Chemical paint removers – can raise grains, be expensive, and potentially volatile; runoff can be hazardous
- Flame tools, blow torches to soften paint – smoldering sparks can potentially start a fire; lead components in paint can vaporize and create highly toxic fumes
- Sandblasting – can be abrasive to surface, wear away protective exterior coating and raise the wood grain
- High-pressure water wash – forces water into open joints affecting interior finishes and structural framing; can be abrasive to exterior surface and raise the grain

Evaluation, Effect on Historic District, Recommendations: The proposed work conforms with the intent of the Secretary of the Interior's Standards for Rehabilitation and the Bethlehem Historic District Design Guidelines and will have no negative impact to the historic district.

A handwritten signature in black ink that reads "H. Joseph Phillips". The signature is written in a cursive style with a large, looped "P" and a distinct "H".

Date of Meeting: July 10, 2024

By: **H. Joseph Phillips**
Title: **Historic Officer**