




SOUTH FACADE



EAST FACADE



NORTH FACADE



NORTH FACADE - existing fence and steps to be removed. Replace with new concrete steps and railings.



WEST FACADE - before the ada ramp.



WEST FACADE - after ada ramp.



EAST FACADE - siding and plywood removed to reveal materials behind it. What was found was deteriorated wood and framing inside window openings that were used to install the plywood and siding.



EAST FACADE - siding and plywood removed to reveal materials behind it. What was found was deteriorated wood and framing inside window openings that were used to install the plywood and siding.